

To: LM, Narasimman[LM.Narasimman@epa.gov]; Witt, Sue[Ex. 4 - CBI] Kling, Timothy[Ex. 4 - CBI]; Brannon, John[Ex. 4 - CBI] Sojda, Nicole L[Ex. 4 - CBI] Jahne, Michael[Jahne.Michael@epa.gov]; Stuart, Brittany[Stuart.Brittany@epa.gov]; Britt, Ginger[Ex. 4 - CBI]
Cc: Hall, John[Hall.John@epa.gov]; radha.krishnan[Ex. 4 - CBI]
From: Meiners, Greg
Sent: Thur 3/15/2018 6:21:28 PM
Subject: Red String YSI 556 for WaterGen Monitoring
[Red String YSI 556 022818.pdf](#)

Aptim sent the the red string YSI 556 to Fondriest Environmental for maintenance and calibration. The connector assembly, cable assembly and pH/ORP probe were replaced to the tune of \$1,300. In addition, a factory calibration was performed.

Attached, please find the calibration report. I will copy this and paste it in the WaterGen log book.

APTIM

Greg Meiners

Ex. 4 - CBI

www.aptim.com